SWJ-320S series firmware version 2.00 has been released.

October 10 2012

Changes

Update version	Current version
2.00	1.10

Changing the below functions.

No.	Contents
1	MAPS function is added. * Refer to "Operation Manual(MAPS)" and "Product Guide(MAPS)"
2	In order to execute the maintenance after checking that ink fills out into a sub tank, ink supply is started automatically before executing the maintenance function.
3	In order to avoid hitting a carriage and wiper, when finishing [CARRIAGE OUT], the initial movement is executed after the wiper moves to standby-position.
4	Intermittent control function of purge is added for checking the ink in sub tank during the purge pressure. * The LED light turn on or off intermittently.
5	While downloading the parameter of different version, the F/W operates correctly.

Improvement of the below-shown defects.

No.	Contents
1	In case of using Central-IO PCB (MP-E000013) which [E000013-03] is sealed, the "SYSTEM HALT 17b:PCB CIO" error has been occurred when starting from the sleep mode.
2	Immediately after stopping the test printing, there was a case where feeding the media more than required.
3	Impossible to upgrade to the EPL common F/W ver.